Operating Manual



Laboratory Safety

- Users are required to have passed Cornell's on-line laboratory safety training courses particular to this lab before they can use the Gemini 500 SEM.
- Users must fill out a CCMR Shared Facility Access Form
- Do not bring any chemicals or hazardous samples into the lab.
- Take specimens, stubs, and raw material with you when you leave.
- Isopropanol and Aero-Duster are supplied for your use. Wear safety glasses before using them.
- Do not use your card to let others into the SEM lab.

Users failing to follow safety rules will be denied access to the lab.

In case of fire leave immediately and close the door behind you. Do not use the elevators.

Introduction





Sigma 500 SEM part of the CCMR EM Facility

Introduction

Phil's Golden Rule

If ANYTHING does not even SEEM right, leave everything as it is and call Phil (607-279-9480) leave a message if call is not answered. If Phil cannot be reached by phone then use text or email

Laboratory Policies

- · Do not attempt to repair or remove ANY part of the microscope
- Do not add any software or hardware to the computer
- Flash Drives (Memory Sticks) are forbidden
- Data MUST be transferred via Cornell DropBox.
- Do not change the room temperature or bring food or drink into F-3.
- · Wear gloves when touching the shuttles and specimens.
- All samples must be dry and the same height.
- If you sign up and then cannot use your time, cancel your time via FOM 24 hours ahead of time or contact Mick at least one weekday before your scheduled time. Failure to cancel in time will result in use charges.
- Failure to show up without canceling, unless due to illness or other emergency, can result in use charges
- If you are more than 30 minutes late then the microscope becomes available to other users.
- If you feel sick, please reschedule your session. You will not be charged if you stay home due to illness.

Data Storage

- · Data storage and safety is not guaranteed
- Users are responsible for their data, and must copy their data in a timely fashion.
- Periodically the hard drive will be erased.

How to acknowledge CCMR in publications

When research is published using data from this microscope, the facility and the grant number must be acknowledged:

"This work made use of the electron microscopy facility of the Cornell Center for Materials Research (CCMR) with support from the National Science Foundation Materials Research Science and Engineering Centers (MRSEC) program (DMR-1719875)."

Laboratory Access



Problematic Samples

Some samples pose special problems to the SEM and must be avoided or prepared very carefully.

Moist or wet samples

Moist or wet samples are not allowed at all in the SEM.

Magnetic samples

Magnetic samples are not allowed in the SEM without consultation with Mick

Powder samples

All powder samples must be blown off.

All powder samples must be coated with gold/palladium or carbon

All powder samples shall not go closer than 4mm to the pole piece.

Introduction

About this manual

This is a *limited use manual* intended to help new users get started on the Zeiss Sigma 500 SEM. It provides information on basic imaging, column setup, and saving and annotating images. It is not intended to be exhaustive, and there are many principles about scanning electron microscopy and features of this microscope that are not covered by this manual. This manual will be updated and expanded as needed.

Starting the software

Log into CCMR-FOM

Log into SmartSEM

Vacuum -> 🧹 Check: Gun -> EHT ->

Mount your samples onto a shuttle

Х

The Rod Retracted LED and the Store LED should be lit.

Push the VENT button on the load-lock.

About 10-15 seconds later, gently pull the door open.

Slide the shuttle onto the Teflon loading plate. The screw hole should point towards the load arm.





AD INS







Loading your sample

Push rod gently to engage the shuttle

Rotate the rod clockwise until snug

When it is snug the shuttle and the rectangular block will be touching as shown at right.

Note that a small cylinder will fit the slot.









Loading your sample

Close Load Lock door and push the EXCHANGE button



When the vacuum in the Load- Lock is low enough, the valve will automatically open and the light will turn on.



Loading your sample

Push the rod into the chamber to load the Shuttle.

You will feel a hard stop, then rotate the knob on the load arm counter-clockwise at least 5 turns.

Pull the load arm out until you hear and feel a click.









Loading your sample

Important! After you pull the rod out the Rod Retracted light must be on or you have not pulled the arm all the way out.



Push the RESUME button. The light in the load lock will turn off and the valve will close.



Checking the vacuum

Confirm that the vacuum levels of the gun and system are as follows:

- Gun: Less than 2X10⁻⁹ mbar
- System: Less than 4x10⁻⁶ mbar

If the vacuum does not reach these levels contact Mick

GeminiSEM Control
Control Imaging Gun Vacuum Stage
0 mml
General
Vac Status = Ready
EHT Vac ready = Yes
Column Chamber valve = Open
Gun Vacuum = 1.02e-09 mbar
System Vacuum = 1.51e-06 mbar
Chamber = 6.84e-01 Pa
Chamber Status = at HV
Beam sleeve Aperture = Beam sleeve 800 µm
Pump
Partial Vent on Standby
Vac Quiet Mode



Operations

Positioning your sample

Click on the Center icon. This will move your sample to the middle of X-Y travel

Use the Zoom View slider to magnify the image of your sample holder

Select your sample holder from the dropdown menu:







Operations

Positioning your sample

Click on the TV1-TV2 button to go back and forth between the two different cameras.

Use the Z-control to move the sample to about 4mm from the end of the pole piece. Set the WD to 4 mm.





Click on the EHT icon and set the EHT to the desired value

Turn on the EHT

Set Signal A = InLens

Set the Scan Speed = 3

Set the Noise Reduction = Pixel Average.

You should now see an image on the screen.



Settings

Ŧ

Signal A = USB TV1

Signal B = HE-SE2



*

Sigma	500	SEM
-	CCMR	part of the EM Facility

Gemini SEM Control

Column

Control Imaging Gun Vacuum Stage

EHT On EHT Off I Blank

Operations

Imaging

When you first turn on the beam you may not see anything at all. Some reasons are:

- 1) You are not over your sample.
- The brightness and/or contrast may not be set properly
- Your working distance (WD) may be too short (0.0 mm) or too long (Focus). Try setting WD to 4 or 5mm
- Your magnification may be too high, set it as low as possible





Operations

Imaging

Once you can see an image of your sample, it is still very unlikely that it is optimized, so you must follow the procedure below.

Start with a reasonably focused image.

Rotate the focus knob back and forth (over focusing and under focusing the beam)

If objects in the field of view move back and forth, then the aperture is not centered.

Centering the aperture:

- 1. Set the scan speed to 1 or 2
- 2. Click on Aperture
- 3. Click on Focus Wobble
- Click on the up/down and left/right arrows to stop the motion





Operations

Imaging

 If the object stretches as you go through focus, first one way, then the other, you have stigmatism which must be corrected



Imaging – complete process

This process needs to be checked and repeated:

- 1) As you increase the magnification
- 2) After you move to a new area
- 3) Any time you want to make sure you are getting the best image possible.



Operations

Imaging – taking the image

To take an image go to the imaging tab and in the Noise Reduction section choose either:

- 1) Line Integrate
- 2) Drift Compensated Frame Integration

For Line Integration a typical setting is:

Scan Speed = 3

N = 100

For Drift Compensated Frame Integration a typical setting is: Scan Speed = 1 N = 50

These are just suggested starting values; the best values for your sample could be quite different.

Control Imaging Gun Vacuum Stage Store resolution = 1024 * 768 • Scan Speed = 6 • Cyde Time = 2.8 Secs Spot Line Scan Noise Reduction
Store resolution = 1024 * 768 Scan Speed = 6 Cycle Time = 2.8 Secs Spot Line Scan Noise Reduction Noise Reduction = Pixel Avg. Settings
Scan Speed = 6 Cycle Time = 2.8 Secs Spot Line Scan Noise Reduction
Spot Line Scan Noise Reduction Noise Reduction = Pixel Avg. Settings
Noise Reduction
Noise Reduction = Pixel Avg. Settings
N = 20
Scan Interface = 15
I fintenace
Freeze on = End Frame
Detector / Active Channel
Signal A = USB TV1 Settings
Signal B = HE-SE2

Saving images

To save the first image from a sample:

Click On File -> Save Image



Click on Change Directory

Export TIFF [d:\user\2015\mt57\	manual\]	
Change Directory	Save Settings Filename Sample Next 01	

Click on the year and select your folder (or create a new one)



Operations

Saving images (con't)

After selecting your folder click on Select Folder at the bottom of the window

The following window will appear:

Click in the box below Filename and type in your new filename

Cilck on Digits and type "2" or "3"

Click in the box to the right of Next and type "01" or "001" as appropriate

Click on Save

For subsequent images of the same sample simply click on Save



Change Directory	Save Settings
	Filename
	Sample Next 01
	Format Max 30 Chars Digits 2
	Merge
	Annotation Sample ID =
	Store resolution = 1024 * 768
	User Text
<	
4 111	
Save Sample01.tif	



Turning off the SEM

Go to Gemini SEM Control -> Control -> EHT off

After the EHT is fully off click on 'Exchange' on the console (do not move X, Y, Z or rotation manually – the software will do this automatically).

The stage will move into position and the valve will open.

Gently push the arm in until it engages the shuttle.

Rotate the arm about five turns clockwise until snug.









Pull the arm out until you hear a click.

IMPORTANT! The green "Rod Retracted" LED must be lit.

Click on Resume - the valve will close and the light will turn off.

Resume Complete will show up on the monitor – click OK

Push the Vent button on the load lock.

When the load lock is vented, open the door and remove the shuttle.

Close the load-lock and click on Store







Sigma 500 SEM part of the CCMR EM Facility

Operations

Turning off the SEM

When your sample is removed and the loadlock is pumped back down, go to File ->Exit

When this window appears, click Yes





Transferring data

Click on the User-Image Shortcut and select the appropriate folder

Click on the Data-share Shortcut and select the appropriate folder

Copy your data from the User-Image folder to the Data-share folder

Using Cornell Drop-box transfer your files











Logout

Log off from CCMR-FOM

Reference

Choosing a voltage

Lower voltages tend to produce more surface detail. However lower voltage electrons also tend to make edges a little softer.

Note the differences in the images of gold islands at right, one taken at 2keV, and the other at 20 keV.



2 keV



 Keck SEM
 100 nm
 WD = 6.2 mm
 EHT = 20.00 kV
 Aperture Size = 30.00 µm
 Date :5 Oct 201

 File Name = Tin009.ttr
 Signal A = InLens
 Time :12:28:18

20 keV

Reference

Choosing a detector

The In-Lens detector usually produces the best resolution but can flatten images.

The HESE2 renders a more faithful topographic image but sometimes with less signal to noise.





 200 nm
 WD = 5.3 mm
 EHT = 5.00 kV
 Aperture Size = 30.00 µm
 Date :5 Oct 2016

 Keck SEM
 File Name = Tin002.tif
 Signal A = SE2
 Time :11:36:53

Imaging – line integration



Imaging – drift compensated frame integration



Reference

Positioning your sample

To move the stage in the X-Y direction, use the larger of the two joysticks as shown



To move the stage in the Z direction or to tilt it, use the smaller joystick as shown



Adjustments – stigmatism

Initially, as you go through focus your image probably looks like this:



The goal is to adjust the X and Y stigmators so that the object will look like this as you go through focus:



Reference

Imaging – 2 in 1

In this mode two different signals (e.g. In-Lens and Backscattered) are collected at the same time and displayed in the same window.

To get this click on the 2 in 1 icon on the toolbar

Then click on View -> DataZone -> Load User DataZone -> 2-in1

Return DataZone and imaging mode to "Normal" when finished.





Reference

Imaging – Dual Mag

In this mode two different magnification images are collected and displayed in the same window.

To get this click on the DualMag icon in the toolbar

Then click on View -> DataZone -> Load User DataZone -> DualMag The "Zoom factor" in the DataZone reflects the relative scale A scale bar can be inserted in the magnified image.

Return DataZone and imaging mode to "Normal" when finished.

 Image: Definition of the system of the sy







Choosing an aperture

Low Current Mode			
<u>Aperture (μm)</u>	<u>Probe size (nm)</u>	Current (pA)	
7	1.08	3.5	
10	1.04	6.6	
15	1.66	13.5	
20 (center)	1.1	37	
30	9.3	51.2	
60	71.9	205	
120	574	778	
	High Current Mode		
<u>Aperture (μm)</u>	High Current Mode Probe size (nm)	Current (pA)	
<u>Aperture (μm)</u> 7	High Current Mode Probe size (nm) 3.6	<u>Current (pA)</u> 6.5	
<u>Aperture (μm)</u> 7 10	High Current Mode Probe size (nm) 3.6 2.6	<u>Current (pA)</u> 6.5 12.2	
<u>Aperture (μm)</u> 7 10 15	High Current Mode Probe size (nm) 3.6 2.6 1.9	Current (pA) 6.5 12.2 24.8	
<u>Aperture (μm)</u> 7 10 15 20 (center)	High Current Mode Probe size (nm) 3.6 2.6 1.9 1.5	Current (pA) 6.5 12.2 24.8 40.7	
Aperture (μm) 7 10 15 20 (center) 30	High Current Mode Probe size (nm) 3.6 2.6 1.9 1.5 1.2	Current (pA) 6.5 12.2 24.8 40.7 94.2	
<u>Aperture (μm)</u> 7 10 15 20 (center) 30 60	High Current Mode Probe size (nm) 3.6 2.6 1.9 1.5 1.2 1.9	Current (pA) 6.5 12.2 24.8 40.7 94.2 377	

	Best Imaging Modes	
<u>Aperture (μm)</u>	<u>Probe size (nm)</u>	Current (pA)
20 (low current)	1.1	37
30 (high current)	1.2	94.2
	Best X-ray Modes	
<u>Aperture (μm)</u>	<u>Probe size (nm)</u>	<u>Current (pA)</u>
30 (high current)	1.2	94.2
60 (high current)	1.9	377
120 (high current)	10.1	1440